



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT
Road History Data Sheet

General

Zone

DASARAHALLI

Ward No.

13

Ward Name

Mallasandra

Street ID

I0283, W0091, I0254

Street Name

NA, Om Shakthi Lyt 3rd Crs

Significant Landmark

Opposite Maheshwaramma temple

Segment No.

13/C-I0283/S032415

Total Length (m)

43.05

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	43.05	77.514058	13.047740	77.514433	13.047614	I0254	I0254

Work Details

History of Road / Lane / Circles

Name of the Work

Pipe line Park maintenance in ward no.13 in Shettyhalli Sub Division

Sanctioned Estimated Amount (Rs.)

2500000

Sanctioned Year

2020

Year

2019 - 2020

Type of Work

Others

Other Work Type

Tender

Tender

Work Details

Job No. / Work Code

013-20-000004

Work Order No.

EE/DD/WO/13/2021-22

Work Order Date

07/06/2021

Period of Extention

Defect Liability Period From

22/02/2022

Defect Liability Period To

15/02/2023

Multiple road involved with the same Job No/ Work Code #

No

Contractor Details

Name of Contractor

Kumar D.V

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)

2184838.00

Phone No.

9845187283

E-Mail ID

DASARAHALLI

Ward No: 13

Ward Name: Mallasandra

Street ID: I0283,
W0091,
I0254

Field Inspection Details

Number of Trees

0

Any Other Information

Name

Rudramuni RT

Date of Inspection

25/02/2022

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	03/03/2022	27/03/2022	APPROVED
EE	EE DAS	03/03/2022	27/03/2022	FORWARDED
AEE	Janardhan	03/03/2022	27/03/2022	forwarded
AE	Rudramuni RT	25/02/2022	27/03/2022	forwarded
AE	Rudramuni RT	25/02/2022	27/03/2022	created

Zone: DASARAHALLI

Ward No: 13

Ward Name: Mallasandra

Street ID: I0283,
W0091,
I0254